
## **Replacement Parts & Labels**



REF PAR	Τ#	DESCRIPTION
---------	----	-------------

1	PH8153001	GAS INLET TUBE
2	PH8153002	COLLET BODY
3	PH8153003	GAS NOZZLE #4
4	PH8153004	GAS NOZZLE #5
5	PH8153005	GAS NOZZLE #6
6	PH8153006	LONG COLLET BACKCAP
7	PH8153007	SMALL COLLET BACKCAP
8	PH8153008	COLLET 1.6MM
9	PH8153009	COLLET 1.8MM

REF	PART #	DESCRIPTION
-----	--------	-------------

10	PH8153010	COLLET 2MM
11	PH8153011	TIG TORCH & CABLE ASSEMBLY
12	PH8153012	WORK CLAMP & CABLE
13	PH8153013	ELECTRODE CLAMP & CABLE
14	PLABEL-14	ELECTRICITY LABEL
15	PLABEL-12	READ MANUAL LABEL
16	PH8153016	WELDER ID LABEL
17	PH8153017	SHOCK WARNING LABEL

## **AWARNING**

Safety labels warn about machine hazards and ways to prevent injury. The owner of this welder MUST maintain the original location and readability of the labels on the welder. If any label is removed or becomes unreadable, REPLACE that label before using the welder again. Contact Grizzly at (800) 523-4777 or www.grizzly.com to order new labels.

